

Ronseal Perfect Finish Smooth & Repair – restores damaged walls & ceilings

Ronseal Perfect Finish Smooth & Repair is the ideal way to restore damaged walls & ceilings to leave them super smooth & ready for painting.

This unique formula, used with the Perfect Finish Smoother, has been specially developed to allow the optimum coating for covering imperfections to leave the ideal foundation for painting.

RONSEAL PERFECT FINISH SMOOTHER

The unique smoother is included in the pack, and has been specifically designed to help you achieve the best finish possible. It has a soft rubber edge which helps to smooth out just the right amount of product. And with its rounded edges residual smoothing lines are kept to a minimum which reduces any subsequent sanding. An easy grip handle not only gives better control to help achieve a smooth finish, but also allows all projects however large, to be completed quickly and easily. Ronseal Perfect Finish Smooth & Repair is ideal for repairing and smoothing damage to walls and ceilings, including gaps, cracks and holes up to 5mm wide and

2mm deep. It can also be an easy substitute for putting up lining paper or applying a textured finish to cover up imperfections.

PREPARATION

Ensure the wall or ceiling is free of any loose particles or mould. It should be sound and clean. Seal in all stains using an appropriate stain sealer or damp seal. Fill in any large holes or cracks over 5mm wide or 2mm deep with an appropriate wall filler and leave to dry. For best results remove all nails and screws prior to application. Assemble the Ronseal Perfect Finish Smoother.

APPLICATION

- 1 Stir the product to a creamy consistency. Use a short pile roller to apply. Sink the roller head into the product to fully load it up. Apply liberally to a small area. Reload the roller and repeat the application until an area of approx. 1m² is covered. Do not roll out the product too thinly. The surface is now ready for smoothing.
- 2 Using the Ronseal Perfect Finish Smoother, place the blade vertically and at a 45 degree angle to the wall. Maintaining this angle pull the Smoother across the wall. The best results are achieved by ensuring you drag the Smoother throughout the process, ensuring

an even pressure. The optimum amount of product should be left on the wall, and fill any imperfections to leave a super smooth finish. The excess product on the smoother can be returned to the pack for subsequent application, minimising any waste. Repeat across your wall or ceiling until surface is totally smooth. Apply a 2nd coat if necessary leaving 6-8 hours between coats, repeating the application process.

- 3 The surface should be ready to paint after only 6-8 hours. Any residual smoothing lines can easily be sanded to leave a perfectly smooth finish.

CLEAN UP

Remove as much product as possible from the tools before cleaning. Simply wash the tools out in warm soapy water immediately after use. Do not empty product into drains or watercourses. Some local authorities have special facilities for disposal of waste coatings.

COVERAGE & DRY TIMES

2.5 litres will cover 5m² assuming an average thickness of 0.5mm and should be dry in 6-8 hours in normal conditions. A thicker coating or colder conditions may extend the drying time up to 24 hours.

FOR FURTHER ADVICE PLEASE CONTACT:

RONSEAL TECHNICAL SERVICES,

Tel: 0114 240 9469

Ronseal Ltd, Thornclyffe Park,

Chapelton, Sheffield. S35 2YP

Tel: 0114 246 7171 Fax: 0114 245 5629

enquiry@ronseal.co.uk www.ronseal.co.uk

RONSEAL AND RONSEAL DOES EXACTLY WHAT IT SAYS ON THE TIN ARE REGISTERED TRADEMARKS OF THE SHERWIN-WILLIAMS COMPANY © 2010. MADE IN U.K.



2.5 litre e



800013140011111-0045

HEALTH & SAFETY

Keep out of the reach of children. Avoid contact with skin and eyes. After contact with skin wash immediately with plenty of water. In case of contact with eyes, rinse immediately with plenty of water and seek medical advice. Use only in well ventilated areas. Avoid the inhalation of dust, wear a suitable face mask when sanding.

Wise precautions: To avoid risk of spillage, always store and transport in a secure and upright position. Protect from frost. Do not apply below 10°C or in high humidity.



EU limit value for this product (cat A/a): 75 g/l (2007)/30 g/l (2010).
This product contains max. 4g/l VOC.